


PRODUCTION FLOW



Production stage	
1	Iron ore mining
2	Sintering
3	Blast furnace
4	Basic-oxygen furnace
5	Ladle furnace
6	Vacuum degasser
7	Continuous casting machine
8	Reheating furnace
9	Mill 2000
10	Continuous pickling line
11	Cold-rolling mill
12	Hot-dip galvanizing line
13	Polymer coating unit
13	Cutting machines
14	Finished products in coils